



Hyatt Regency Jerusalem
32 Lehi Street
Jerusalem 97856, Israel

Phone: (02) 533-1234
Fax: (02) 581-5947

23 February, 1997

TO WHOM IT MAY CONCERN,

Re: HYDOFLOW WATER CONDITIONER

We hereby confirm that an electronic water conditioner HYDOFLOW C-160 was installed over two years ago on a 6" pipe of the hot water (consumable) system supplying to all our 500 rooms.

We confirm our full satisfaction with the results of the treatment.

Yossi Kalev
Director of Engineering
Hyatt Regency Jerusalem


TO WOM IT MAY CONCERNRe: HYDROFLOW WATER CONDITIONER

We hereby confirm that an electronic water conditioner HYDROFLOW C-60 was installed during March 1993 on a 2" pipe of the hot water (consumable) system supplying to all our 307 rooms, at our Radisson-Moriah Eilat Hotel.

The system was opened once each year since then for check-up. The pipes, reservoir tanks and installation accessories (valves, filters etc.) were examined and found to be clean of any scale deposits to our full satisfaction.

Thus, we have decided to install the HYDROFLOW units in all our 8 hotels in Israel - 4 during 1997 and 4 during 1998 - on hot water systems and cooling water (air conditioning) systems.

Eng. Avi Ben-Zeev

Chief Engineer
Radisson Moriah